

Modernizing Airport Tenant Inspections

By Sirisha Muppala



Located in the heart of Silicon Valley, San José Mineta International Airport (SJC) transformed its process for managing tenant inspections from a manual data collection process to one that is GIS based.

Managing Airport Tenants

SJC is an international airport that encompasses 1,120 acres, hosts 11 commercial airlines, and sees approximately 12 million passengers pass through its gates each year. Airports are often referred to as cities, given the multifaceted nature of their operations and the diverse spaces they encompass. Central to this characterization is the pivotal role of interior space maintenance, as it significantly contributes to creating a welcoming environment for passengers within these bustling hubs.

SJC carries out regular inspections of its spaces leased or rented by retail shops, restaurants, and service providers to evaluate their condition and compliance with contracts. Inspections cover the safety, cleanliness, and general maintenance of tenant spaces. The goal is to ensure that all tenant areas meet the airport's standards and regulatory requirements.

Maintaining operational excellence is paramount. For years, dedicated property managers relied on manual data collection

methods to conduct quarterly tenant inspections. Each inspection involved handwritten notes and manual data entry into Microsoft Excel spreadsheets.

Inspection findings were communicated through lengthy email chains, leading to inefficiencies and occasional errors. The system, while functional, was far from optimal. Another challenge encountered by property managers using manual methods was the absence of a systematic process for tracking inspection follow-ups. In addition,

← Terminal B North Concourse at San José Mineta International Airport



although inspection findings were communicated, there was no integrated mechanism to monitor the completion status of the required repairs.

As the airport grew, the limitations of this manual process became increasingly apparent. The property management team faced numerous challenges: data inaccuracies, delayed reporting, insufficient tracking of identified repairs, and a cumbersome workflow that struggled to keep pace with the dynamic needs of a modern airport. It

was clear that a change was necessary to elevate operations.

Recognizing the potential of technology to revolutionize its processes, SJC embraced a new survey system that integrated GIS into the process of tenant space inspections. By leveraging GIS technology, SJC aimed to streamline inspections and ensure a proactive and systematic approach to facility maintenance.

Food and beverage outlets and retail stores are vital commercial spaces at SJC. Maintaining the cleanliness of these spaces is critical. The move from manual to digital concession inspections began with these tenants, although the plan is to eventually employ digital methods for the inspection of all tenant spaces, including airline offices, service providers, and maintenance facilities.

The Role of GIS in Streamlining Airport Business Processes

Ten years ago, SJC implemented GIS technology to oversee the geospatial data associated with the airport, including data on runway and taxiway layouts, airfield signage and lighting, passenger terminals, aircraft parking stands and jet bridges, baggage handling areas, building footprints, and utilities.

Recently, there has been a concentrated effort to integrate the geospatial data with other business processes or systems within the airport. GIS at SJC was migrated from a stand-alone ArcGIS Server to ArcGIS Enterprise, which made tools such as ArcGIS Survey123 available.

GIS was adopted to modernize and enhance the efficiency of managing tenant spaces by centralizing data management and consolidating all tenant inspection data into a single, accessible platform. As part of this comprehensive integration strategy, the survey system is seamlessly linked with GIS.

The airport's GIS team conducted a comprehensive analysis. They examined ways to modernize and identify areas where GIS data can be used to streamline the inspection data collection process. As a result, the GIS team proposed implementing ArcGIS Survey123, a form-centric data gathering

GIS method, as a transformative solution to replace handwritten survey notes.

Transforming Workflows for Efficiency

The strategy employed for implementing ArcGIS Survey123 divided the implementation process into three phases: 1) analysis and migration; 2) pilot testing and user adoption; and 3) full deployment and optimization.

Analysis and Migration

The transition began with a comprehensive analysis of the existing workflow. Previously, the procedure entailed using a paper form created in Microsoft Excel to evaluate tenant maintenance activities across categories such as customer service, facility, and equipment, back-of-house procedures, and exterior appearance. Each metric was subdivided to furnish detailed information on specific elements. These field observations were entered manually into a computer, and the inspection findings were emailed to tenants.

Subsequently, this entire process was migrated to ArcGIS Survey123 and integrated with the GIS database containing tenant information, so that it became the primary repository for that information. Criteria were systematically organized into user-friendly drop-down menus within ArcGIS Survey123 to facilitate scoring. An overall score field was added for each metric in the inspection findings, along with a new field to compute the total possible score for each concession, which represented the highest achievable score for tenants. This system provides a comprehensive overview and aligns the new system with the current workflow.

Pilot Testing and User Adoption

To maximize the effectiveness of the new methodology, pilot testing was initiated in June 2023. Over three months, a select group of users with the Survey123 system installed on Apple iPad devices conducted extensive testing. Valuable feedback was incorporated into ArcGIS Survey123, ensuring that the changes implemented addressed the practical needs and concerns

CONCESSION			TOTAL SCORE : _____ / 110	
	AUDIT ITEM	RANGE / ITEM SCORE	COMMENT	
CUSTOMER SERVICE				
1	HOURS OF OPERATION: Store is open for business as required during normal business hours	0-5		
2	STAFFING: Staffing levels are adequate to provide prompt customer service at all times	0-5		
3	APPEARANCE: Personnel are well-groomed, dressed appropriately in clean clothes or are wearing the full and correct uniform when on duty, including name badge	0-5		
4	APPEARANCE: Staff is not drinking, eating or chewing gum	0-5		
5	APPEARANCE: Employees are actively working while on duty and are not using cell phones or discussing personal matters	0-5		
6	SERVICE: Customers are acknowledged by staff with a friendly greeting within ten seconds of arrival and are greeted as they walk through the shop	0-5		
7	SERVICE: Employees who are engaged in non-customer service needs quickly shift to greet customers as they enter the store, offer assistance or ring sales	0-5		
8	SERVICE: Employees demonstrate a positive attitude, upbeat and eager to help customers	0-5		
9	PRICING: All displayed items for sale are appropriately signed and/or priced	0-5		
10	SERVICE: Average wait time is less than 3 minutes per customer	0-5		
SCORE		50		
FACILITY AND EQUIPMENT				
1	Floors are clean; no damage to floor tiles or epoxy, coving, and grout	0-5		
2	Light fixtures are illuminated during operating hours	0-5		
3	Areas are free of visible dust	0-5		
4	Grab 'n go coolers are working and in like new condition	0-5		
5	Entrance isn't too blocked/cluttered by display racks	0-5		
6	Extra stock of product is not visible to the passengers	0-5		
7	Clean and restock condiments stations and grab 'n go areas are clean	NA NA		
SCORE		30		

identified during the testing phase. Iterative feedback allowed for the identification and resolution of any issues and inclusion of any adjustments and improvements needed before full-scale implementation.

Concurrently, a robust training program was executed to familiarize all relevant personnel with the new system, ensuring a smooth transition and minimizing disruptions. This training was crucial in preparing the staff for the changes and ensuring they could use the new system effectively.

Full Deployment and Optimization

Following the successful completion of pilot testing and training, the project moved to the final phase in March 2024. It focused on the full deployment of ArcGIS Survey123 to all users. Continuous monitoring and feedback mechanisms were established to address any unforeseen challenges during the initial stages of widespread use.

With the final deployment of ArcGIS Survey123, all users had a dynamic and automated communication channel to inform tenants of inspection results. Using Microsoft Power Automate, an email was issued after a survey was submitted. The email included detailed information such as ratings and inspection photos from the survey. This automated communication ensured timely and accurate dissemination of

↑ The inspection workflow and metrics as originally captured in a spreadsheet.

→ Criteria were systematically organized into user-friendly drop-down menus within ArcGIS Survey123 to facilitate scoring.

UNIT TYPE*
Is this a food and beverage or a retail unit?

Food and Beverage Retail

Tenant*

CUSTOMER SERVICE

1. Hours of Operation: Store is open for business as required during normal business hours*

2. Staffing: Staffing levels are adequate to provide prompt customer service at all times*

3. Appearance: Personnel are well-groomed, dressed appropriately in clean clothes or are wearing the full and correct uniform when on duty, including name badge and is not drinking, eating or chewing gum*

inspection results, further streamlining the process, and enhancing overall efficiency.

The Benefits of the Move to Digital Methods

By adopting ArcGIS Survey123, the airport property managers were able to automate

data collection, streamline inspection processes, and enhance overall operational efficiency. This integration reduced data collection errors and improved tenant space management. It also provides insight into operations by monitoring compliance with lease agreements and regulatory requirements,

FACILITY AND EQUIPMENT ➔

BACK OF HOUSE ➔

EXTERIOR AND MISCELLANEOUS ➔

Overall Score
0

Total Possible Score
0

Overall Inspection Summary

Photo
1 Select image file (maximum number of files allowed: 10)

Submit

↳ An overall score field was added for each metric, along with a new field to compute the total possible score for each concession, which represents the highest achievable score for tenants.

↳ Sirisha Muppala



maintenance, and required repairs.

Real-time visibility into the outcomes of inspections helps airport property managers quickly identify and address issues within tenant spaces such as safety violations. This visibility helps mitigate potential risks and prevent minor problems from developing into major issues that could adversely affect airport operations.

The successful implementation of ArcGIS Survey123 not only modernized the inspection workflow but also aligned with the airport's strategic goal to innovate by leveraging technology and fostering a culture of innovation. The benefits from the new data collection methodology included substantial time and cost savings.

Previously each inspection took several hours to complete. The time for inspections was reduced by 50 percent. Data accuracy was increased by 80 percent and reporting speed was reduced from days to hours or minutes. This led to enhanced decision-making and significant improvements in strategic collaboration. These benefits allow for the timely resolution of issues and judicious allocation of resources. This transformative journey, which began in November 2022, was completed in March 2024.

Conclusion

With the cumbersome process of gathering and analyzing inspection data streamlined, the property management team can focus on strategic decision-making rather than being bogged down by administrative tasks. The integration with GIS established a centralized platform for data collection, analysis, and reporting and provides real-time insights that enhance efficiency and accuracy. This advanced system not only modernized the inspection workflow but also improved tenant space management, integrating seamlessly with GIS data to elevate overall operational standards.

About the Author

Sirisha Muppala, GISP, is the senior GIS specialist for the San José Mineta International Airport. For the past eight years, she has been involved in developing the airport-wide GIS program. During this time, she led the migration to ArcGIS Enterprise. Prior to her role with the airport, she was a water resources scientist at HDR Engineering Inc., and worked with several local governments in California. She holds a master's degree in civil engineering.

For more information, contact

Sirisha Muppala, Senior GIS Specialist
San José Mineta International Airport
City of San Jose
1701 Airport Blvd. Ste B-1130
San Jose, California 95110
Email: smuppala@sjc.org

Managed ArcGIS® Enterprise Services

Let Experts Handle the Complexity

- Security & Compliance
- 24x7 Monitored Environment
- ArcGIS & Windows Patching
- ArcGIS Expertise & Support
- Reliability & Performance
- Fixed-rate Pricing Model
- Pricing starts below \$2,000/mo.

DigitalDataServices.com/mages



DDS
DIGITAL DATA SERVICES, INC.

 **esri** Partner Network Silver

Esri trademark provided under license from Esri